Forest Industry Safety Alert

Fire Extinguisher Maintenance

Location: North Campbell River

Date: March 1, 2017

Details of Close Call:

A mechanic was performing the regular maintenance inspection on a fire extinguisher at a dryland sort.

The gauge was checked and the needle was in the green zone. The date was marked on the tag and then the fire extinguisher was flipped over. In order to ensure the powder content had not settled and packed in the bottom, the mechanic tapped the bottom of the extinguisher with a rubber mallet.

The fire extinguisher exploded and shot the bottom end and the content 50 feet, narrowly missing the mechanic.

Learnings and Suggestions:

- Ensure that eye protection is worn and perform maintenance in a safe area to prevent injury to self and others.
- Check that the gauge needle is in the middle of the green zone.
- Ensure the pin and tamper seal are intact and nozzle has not been hindered in any way.
- Wipe clean the cylinder to remove any dirt or grease.
- Inspect the cylinder, there should be no dents, leaks, rust, chemical deposits and/or other signs of abuse or wear.
- If the extinguisher is damaged or needs recharging, replace it.
- Recharge all extinguishers immediately after use regardless of how much they were used.
- Shake the extinguisher or gently tap with a rubber mallet after thorough examination.

For more information on this submitted alert:

Chris@mountsicker.com

Forest Industry Safety Alerts are voluntarily submitted by workers or companies. The BC Forest Safety Council is not responsible for accuracy of content. Please contact the contributing source regarding incident details. We encourage the sharing of information that can help improve safety for all workers in forestry. NOTE: Providing your contact information is optional. We ask for this contact information so other companies can talk with someone to get further details on the close call / serious incident.

Page 1 of 1

