


Hazard Alert: Broken Excavator window

What happened:

While loading a rock truck with shot rock, an excavator's front window shattered from a piece of broken shot rock. The shattered window showered the operator with broken glass.



Findings:

- Some newer excavators are coming equipped with tempered front windows not safety glass.

Solution:

- A window film made by 3M called Safe and Secure can be applied to the inside of a tempered windshield that will hold it together if it is broken.