

SAFETY / HAZARD ALERT

Dusty Conditions on FSR

Location: Bamfield (west Vancouver Island)

Date of Incident: June 5, 2020

Details of Incident: A driver, experienced with operating on resource roads, drove in to the back of a logging truck that was travelling in the same direction. Reports indicate that the dusty conditions limited visibility. Luckily the driver was not seriously injured.

Recommended Preventative Actions:

- Drive to conditions (including limited visibility)
- Give yourself adequate time to reach your destination
- Travel with headlights and taillights turned on
- Report unsafe conditions to the appropriate road permit holder

For more information: Resource Road Driving <http://www.bcforestsafe.org/node/2634>

